

VEHICLE INSPECTION REPORT

HX65UZF

Mercedes-Benz Sprinter 513 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Photocopy

Details

Reg. date 13/11/2015

Year 2015

Mileage 164,469 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9066552P175326

Body Style Crew Van

MOT Due 30/04/2026

Gearbox MANUAL

SINGLE SIDE DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Navigation system
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Qtr Panel osr
Rusted
Over 5mm



4: A Post os
Chipped
Multiple Chips



5: Switches And Controls
Broken
Replace



6: Other
M

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK