

VEHICLE INSPECTION REPORT

PE63NLR

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 03/12/2013

VIN XLRAE45FF0L433236

Gearbox MANUAL

Year 2013

Body Style Box Van

Axle Combi 4x2

Mileage 779,639 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type Diesel

MOT Due 28/02/2026

Tail Lift Cantilever

Colour RED

Cab Type DAY CAB

COLLECTED AS NON RUNNER - CORROSION

Tyres

NSF NSI1 NSI2 NSI3 NSI4



OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Other
N/A
N/A



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Wing nsf
Scratched
UpTo 25mm Not Thru Paint



8: Other
N/A
N/A



9: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



10: Other
N/A
N/A



11: Door Mirror Assy nsf
Broken
Replace



12: Bumper Rear
Rusted
Holed



13: Other
N/A
N/A



14: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



15: Door osf
Scratched
UpTo 25mm Thru Paint



16: Door osf
Chipped
Edge Chip



17: Seat Base Cover osf
Holed
Over 3mm



18: Seat Base Cover osf
Holed
Over 3mm



19: Other
N/A
N/A



20: Other
N/A
N/A



21: Fascia Panel
Missing
Replace

22: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	