

## VEHICLE INSPECTION REPORT

**BX59DGO**

### Daf LF 45.160

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 To Follow

#### Details

Reg. date 10/11/2009

VIN XLRAE45FF0L353861

Axle Combi 4x2

Year 2009

Body Style Box Van

Rear Suspension Steel

Mileage 98,675 Km Warranted

MOT Due 30/11/2025

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Colour WHITE

Gearbox MANUAL

WORKSHOP, KITCHENETTE, SEATING, GAS HOB, SINK, SIDE LOAD DOOR

#### Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4


## Features

- Cruise control
- Front electric windows
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Panel Front  
Cracked  
Replace



2: Bonnet  
Chipped  
Multiple Chips





3: Bumper Front Grill  
Broken  
Replace



4: Bumper Front  
Rusted  
Over 5mm



5: Door nsf  
Dented  
Over 30mm



6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel Moulding os  
Broken  
Replace



8: Door osf  
Scratched  
Over 25mm Thru Paint



9: Door Pad osf  
Soiled  
Heavy



10: Seat Base Cover nsf  
Soiled  
Heavy



11: Dash Warning Lights  
Displayed  
No Action

### Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		