

VEHICLE INSPECTION REPORT

PN18DBV

Iveco Daily 35-140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/04/2018

Year 2018

Mileage 136,471 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFCC35AX0D597005

Body Style Dropside MWB

MOT Due 26/04/2026

CAP Clean £5,000.00

CAP Average £4,300.00

CAP Below £3,350.00

Gearbox MANUAL

Gears 6

Tail Lift Column

VEHICLE RUNS & DRIVES, COLLECTED WITH HEAD GASKET ISSUES 3450 WB

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
Up To 100mm



3: Bonnet
Chipped
Multiple Chips



4: Screen Front
Chipped
UpTo 10mm



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Other
N/A
N/A



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



10: Carpets Front
Holed
Over 3mm



11: Seat Base Cover osf
Torn
Over 3mm



12: Other
N/A
N/A



13: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK