

VEHICLE INSPECTION REPORT

VX16AEC

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 04/04/2016

VIN SEG2628HR6BG21597

Axle Combi 6x2

Year 2016

Body Style Refuse Collector

Steering Combi Rear-Lift Steer

Mileage 63,741 Km Warranted

MOT Due 31/10/2025

Rear Suspension Steel

Fuel Type Diesel

Cab Type CREW CAB

Colour WHITE

Gearbox AUTOMATIC

WARNING LIGHT ON DASH OLYMPUS TP22 BODY, TERBERG SPLIT LIFT

Tyres

NSF NSI2 NSI3 NSI4

OSF OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Bumper Front
Poor Previous Repair
Poor Paint



2: Moulding of Wing
Scratched (Painted)
Over 25mm Thru Paint



3: Bonnet
Poor Previous Repair
Poor Colour



4: Bonnet
Poor Previous Repair
Poor Paint



5: Bumper Front
Poor Previous Repair
Poor Paint



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Other
N/A
N/A



9: Flasher Side Repeater ns
Broken
Replace



10: Other
N/A
N/A



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



12: Seat Base Cover osf
Torn
Over 3mm



13: Seat Base Cover nsf
Holed
Over 3mm



14: Seat Base Cover nsf
Holed
Over 3mm



15: Seat Back Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average	Average	Average	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK