

VEHICLE INSPECTION REPORT

FJ72VRD

Mercedes-Benz eVito 85kW 66kWh Progressive Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/11/2022

Year 2022

Mileage 49,104 Miles Not Warranted

Fuel Type Electric

Colour WHITE

VIN W1V44760324137980

Body Style Panel Van L2

MOT Due 09/11/2025

CAP Clean £9,950.00

CAP Average £9,200.00

CAP Below £7,925.00

Gearbox AUTOMATIC

TWIN SIDE LOAD DOORS, E/MIRRORS, HEATED WINDSCREEN

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Rear parking sensor
- Air conditioning
- Central locking
- Cruise control
- Digital radio
- Front electric windows
- Cloth seat trim
- Navigation system
- Mobile phone App interface
- Drivers airbag
- Park assist camera
- Radio/CD
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bumper Front
Missing
Replace



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Door osf
Dented
With Paint Damage



4: Panel Rear
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
With Paint Damage



7: Door nsr
Dented
Over 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Panel Rear
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Panel Front
Scratched
Over 25mm Thru Paint



12: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



13: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK