

VEHICLE INSPECTION REPORT

VX16AEG

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 11/04/2016

Colour WHITE

Gearbox AUTOMATIC

Year 2016

VIN SEG2628HR6BG21601

Axle Combi 6x2

Mileage 74,331 Km Warranted

Body Style Refuse Collector

Fuel Type Diesel

Cab Type CREW CAB

WARNING LIGHT ON DASH OLYMPUS TP22 BODY, TERBERG SPLIT LIFT

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Colour



2: Bonnet
Poor Previous Repair
Poor Colour



3: Other
N/A
N/A



4: Other
N/A
N/A



5: Other
N/A
N/A



6: Bumper Rear
Rusted
Over 5mm



7: Door osf
Chipped
Edge Chip



8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



9: Seat Base Cover osf
Torn
Over 3mm



10: Seat Back Cover osf
Torn
Over 3mm



11: Seat Base Cover nsf
Torn
Over 3mm



12: Seat Base Cover nsf
Torn
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	