

VEHICLE INSPECTION REPORT

PO70VWG

Mercedes-Benz Sprinter 316 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 24/09/2020

Year 2020

Mileage 130,151 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076332P254264

Body Style Panel Van L2

MOT Due 23/09/2025

CAP Clean £9,500.00

CAP Average £8,475.00

CAP Below £6,950.00

Gearbox MANUAL

BATTERY ISSUES, WARNING LIGHT ON DASH, NO ACCESS TO REAR AD-BLUE, SIDE LOAD DOOR, TOW BAR, DEADLOCKS (WITH KEYS)

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Seat Base Cover nsf
Burn
Over 3mm

Interior

Carpets Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		