

VEHICLE INSPECTION REPORT

DV73AOB

Vauxhall Vivaro 3100 2.0D 145PS PRIME

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 25/09/2023

Year 2023

Mileage 19,633 Miles Not Warranted

Fuel Type Diesel

Colour GREY

VIN VXEVFEHTMP7854116

Body Style Panel Van L2

MOT Due 24/09/2026

CAP Clean £13,500.00

CAP Average £12,750.00

CAP Below £11,200.00

Gearbox MANUAL

Gears 6

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Auxiliary input socket
- Metallic Paint
- Cloth seat trim
- Cruise control
- Digital radio
- Drivers airbag
- Park assist camera
- Air conditioning
- Passenger airbag
- Rear parking sensor
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Wing nsf
Scratched
Over 25mm Thru Paint




3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel nsr
Dented
With Paint Damage



5: Door osf
Dented
Over 30mm



6: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		