

VEHICLE INSPECTION REPORT

YR66TSX

Ford Transit Connect 220 1.5 TDCI 100ps

Inspection

Serious Damage? No

Vehicle

VAT

V5 Buyer To Apply

Details

Reg. date 29/09/2016

Year 2016

Mileage 43,496 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXWPGRGD08638

Body Style Panel Van L1

MOT Due 17/12/2025

CAP Clean £3,875.00

CAP Average £3,225.00

CAP Below £2,400.00

Gearbox MANUAL

Gears 5

SIDE LOADING DOOR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
UpTo 10mm



3: Wing nsf
Dented
Between 10mm + 30mm



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK